



**Standard End Machining: Non-Captive and External Linear Actuators**


**Cross Drilled Hole**




**Turned Journal**




**Hex Drive End**




**Male Thread**




**Square End**




**Female Thread**




**Single Flat**




**Screwdriver Slot**



**Double Flat**



**Standard Break Edge**



**Ground Journal**

